Work	Order	ID	58998
------	-------	----	-------

Friday, May 21, 2010 8:41:54 AM



Page 1

Item ID:

D3825-041

Accept



Setup Start

Stop



**Revision ID:** 

Item Name: Rib Assembly (Basket End)

**Start Date:** 5/21/2010

Required Date: 5/31/2010

Start Qty: 6.00

Req'd Qty: 6.00

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:	Process Plan:	
		/

Date: 18-3-21 Tooling:

Date:

Run Start



QC:

Date: SPC (Y/N):

Date:

Stop

Sequence ID/ **Work Center ID**  Operation **Description** 

Set Up/ **Run Hours**  Draw Number

Draw Rev.

Plan

Code

Accept Qty

Reject Qty

Reject Number

Insp. Stamp

Draw Nbr

**Revision Nbr** 

D3825 Rev A

100

Large Fab



Large Fab

0.00

0.00

1- cut D3825-1 rib as per dwg D3825

2- drill hole (3/16") in D3825-1 using DT9438 jig and open to finish size as per dwg D3825

3- c'sink hole as per dwg

4- remove identification markings

5- deburr

Memo

6- weld D2327-3 spacer bushing and D3759-1 bushing as per dwg D3825 A/R S.S. Rod Batch: 11679

7- grind bushing weld flush where indicated on dwg D3825

8- deburr if necessary

Dart	Aer	ospa	ıce	Ltd

	-								τ.
W/O:			WC	RK ORDER CHANGE	S				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
									,
							1		
Part No	:	PAR #:			NCR: Yes	No <b>DQ</b>	A:	Date:	
	Re	esolution:	Disposition	1:	QA: N/C C	losed:		Date:	
NCR:			WORK ORDI	ER NON-CONFORMAI	NCE (NCI	7)			
DATE	STEP	Description of NC			ı B	Verific	cation	Approval	Approval
	0,2,	Section A	Initial Chief Eng	Action Description  Chief Eng	Sign Date		on C	Chief Eng	QC Inspector
									,
***************************************									

Work Order	ID	58998
------------	----	-------

Friday, May 21, 2010 8:41:54 AM



Page 2

Item ID:

D3825-041

Accept

Setup Start

Stop



**Revision ID:** 

Item Name:

Rib Assembly (Basket End)

**Start Date:** 

Required Date: 5/31/2010

5/21/2010

Start Qty: 6.00

Req'd Qty: 6.00



**Cust Item ID:** 

**Customer:** 

Reference:

**Approvals:** 

Sequence ID/

Process Plan: \_\_\_\_\_ Date: \_\_\_\_ Tooling:

Memo

Memo

0.00

0.00

Date:

Run

Start

Stop

QC: \_\_\_\_ Date:

SPC (Y/N):

Date:

Accept

Reject

Reject Insp.

Work Center ID

130

QC

Quality Control

Operation Description

QC9- Inspect visual per OSI004- Fusion Welds

Set Up/ **Run Hours**  Draw Number Draw Rev.

Plan Code Qty

**Qty** 

Number Stamp

(D) D 10.06.04

140

QC

Quality Control

QC5- Inspect part completeness to step on W/O

Identify as per dwg & Stock Location:

150

Packaging Packaging

Memo

0.00 0.00

_		<del></del>							
W/O:			W	ORK ORDER CHANG	ES				•
DATE	STEP	PRO	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector
		,							
Part No	:	PAR #:	Fault Cat	egory:	NCR: Yes	No DQA:		_ Date: _	
		solution:							
NCR:			WORK ORI	DER NON-CONFORMA	NCE (NCR	)			
DATE	STEP	Description of NC	Corrective Action Section Initial Action Description		on B	Verifica		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Date	Section	С	Chief Eng	QC Inspector
				•					
			·						
			•						

#### Work Order ID 58998

Friday, May 21, 2010 8:41:54 AM



Page 3

Item ID:

D3825-041

Accept



Setup Start

Stop



**Revision ID:** 

Item Name:

Rib Assembly (Basket End)

**Start Date:** 

Required Date: 5/31/2010

5/21/2010

Start Qty: 6.00

Req'd Qty: 6.00

Operation

**Description** 



**Cust Item ID:** 

**Customer:** 

Draw

Number

Reference:

**Approvals:** 

Process Plan:

Date:

QC21- Final Inspection - Work Order Release

Tooling:

Date:

Rev.



Date: \_\_\_\_\_ QC:

SPC (Y/N):

Set Up/

**Run Hours** 

Date:

Stop

Start



Sequence ID/

Work Center ID

160

QC

Memo

0.00

0.00

Draw Plan

Code

Reject Accept Qty Qty

Run

Reject Insp. Number

Stamp

Quality Control

10/06/07/94 10-6-4

	•									1	
W/O:			WORK ORDER CHANGES								
DATE	STEP	. Р	ROCEDURE CHAP		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
								-			
Part No	•	PAR #:	Fault Categ	ory:	NCF	R: Yes 1	No DQA		Date:		
		esolution:									
NCR:				R NON-CONFORM				······································			
DATE	STEP	Description of NC	Corrective Action Sect Initial Action Description			Sign &	Verifica		Approval	Approval	
Į.		Section A	Chief Eng	Action Description Chief Eng		Date	Section	n C	Chief Eng	QC Inspector	
					-						
				· · · · · · · · · · · · · · · · · · ·							
								i			
• .											

### **Picklist Print**

Friday, May 21, 2010 8:41:59 AM

Work Order ID: 58998

D3825-041

Parent Item Name: Rib Assembly (Basket End)

Parent Item:

IPP Rev: A 08-12-01 new issue DD verified by EC



WA

114520

**Start Date: 5/21/2010** 

Required Date: 5/31/2010


Page 1

Comments:	IPP Rev:A 08-12-	-01 new issue D	D veri	fied by:EC				!	Start Qty: 6.00		Require	d Qty: 6.0	00
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2327-3		Manufactured	No			100	Each	1.0000	1	6	4	0(16	.06.04
				<u>Locatio</u> WA	<u>n</u> 57790	<u>Loc</u>	Oty i	Loc Code	3	584	06-	->-	6
D3759-1		Manufactured	No			100	Each	36.0000	1	6	- 	0(1	<u>0.06.</u> 0
				<u>Location</u> WA	54072 58159 58256	<u>Loc</u>	Oty 36 9 1 26	Loc Code	B5	8581	<b>\</b>	6	
M304TS0.750W.065		Purchased	No			100	f	1,200.557	J 18801 (68)	13.42105 SAO	10-0	5´.	<del>?</del>
				<u>Locatio</u> MAT	112398 114482	200 200	5571 0	Loc Code	$-\frac{1}{1}$	3. 42 <i>L</i>	15		


1000

1000

	•									Ť.
W/O:			W	ORK ORDER CHANC	GES			<del>- · · · · · · · · · · · · · · · · · · ·</del>		
DATE	STEP	PRO	OCEDURE CHA	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
					:					
Part No	:	PAR #:	Fault Cate	gory:	_ NCF	l: Yes I	No DQA	\:	_ Date: _	
_	Re	esolution:	Dispositio	n:	QA:	N/C Clo	sed:		Date:	
NCR:			WORK ORD	ER NON-CONFORM	ANCE	(NCR	)			
DATE	STEP	Description of NC	Corrective Action Section E			Verifica			Approval	Approval
	0,2,	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector




W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CH	IANGE	Ву	Date (	Qty	<b>Approval</b> Chief Eng / Prod Mgr	Approval QC Inspector					
								·						
Part No		PAR #:												
Resolution:				DER NON-CONFORMA				Date: _						
NCR:			WORK ON		· · · · · · · · · · · · · · · · · · ·	1)								
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Description Chief Eng	ion B Sign 8 Date	Verificat Section		Approval Chief Eng	Approval QC Inspector					
		·												
78	1													



<b>Dart Aerospace</b>	Lt	d
-----------------------	----	---

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DO	QA:	Date: _					
		solution:											
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NC	R)							
DATE	STEP	Description of NC	Description of NC Corrective			Verit	Verification		Approval				
		Section A	Initial Chief Eng	Action Description Chief Eng	Sign Date		ction C	Chief Eng	QC Inspector				
	.												
			·	•									



Dart	Aeros	pace	Ltd
------	-------	------	-----

W/O:			V	<b>VORK ORDER</b>	CHANGE	S			*
DATE	STEP	PROCEDURE CHANGE			,	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						2			
Part No: PAR #:		Fault Category:		NCR: Yes No DQA: Date:					
		Disposition:					Date:		
NCR:		W		DER NON-CON	IFORMA	NCE (NCR	)		
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Des	scription	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector
		.*.		,					